

**Flood Control Project Maintenance
Levee Inspections**

Fall 2011 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin

RD0765	Overall LMA Rating	Total LMA Miles				
Reclamation District No. 0765 Glide	U	1.74				
Rated Item	M Miles	U Miles	M + 4U Miles	Threshold %	Encroachments	
					PO Miles	CO Miles
<i>Earthen Levee</i>						
Vegetation	0.03	0.04	0.19	10.92%		
Trim / Thin Trees	0.84	0.21	1.68	96.55%		
Encroachments	0.01		0.01	0.58%		0.14
<i>LMA Totals:</i>	0.88	0.25	1.88	108.05%	0.00	0.14

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Fall 2011 Levee Inspection Results

Reclamation District No. 0765 Glide

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			U	

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2011 Levee Inspection Results

Reclamation District No. 0765 Glide

Waterway			Bank	Unit Miles
Unit No. 01 Sacramento River			Right	1.74
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			U	
Date of Inspection	3/3/2011 - 3/3/2011		11/10/2011 - 11/10/2011	
DWR Inspector	Richard Willoughby		Richard Willoughby	
Accompanied By	Dave Chestnut RD765		Dave Chestnut RD765	

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0765 Glide

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Sacramento River						Right	1.74	11/10/2011 11/10/2011	Richard Willoughby	
LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.11	Earthen Levee	Encroachments	LS	CO	Fences	38.502962 ° -121.560112 °	38.501373 ° -121.560402 °	12
2	0.05	0.05	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.502253 ° -121.560192 °	38.502253 ° -121.560192 °	3
3	0.12	0.19	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.501215 ° -121.560432 °	38.500271 ° -121.560434 °	28 Y
4	0.14	0.14	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	38.500928 ° -121.560431 °	38.500928 ° -121.560431 °	22
5	0.19	0.35	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.500343 ° -121.560507 °	38.498032 ° -121.560337 °	14
6	0.25	0.28	Earthen Levee	Trim / Thin Trees	WS	U	Thin trees to allow visibility of the ground and room to flood fight.	38.499405 ° -121.560445 °	38.499042 ° -121.560430 °	11 Y
7	0.32	0.32	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.498453 ° -121.560360 °	38.498453 ° -121.560360 °	23
8	0.41	0.41	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.497196 ° -121.560147 °	38.497196 ° -121.560147 °	21
9	0.41	0.52	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.497125 ° -121.560087 °	38.495648 ° -121.559391 °	24
10	0.43	0.47	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.496792 ° -121.560026 °	38.496321 ° -121.559842 °	32
11	0.48	0.50	Earthen Levee	Vegetation	LS	U	Remove the wild growth other than native grasses from the levee slopes.	38.496217 ° -121.559788 °	38.495855 ° -121.559586 °	33 Y
12	0.54	0.54	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.495347 ° -121.559291 °	38.495347 ° -121.559291 °	34
13	0.57	0.60	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.495035 ° -121.559027 °	38.494642 ° -121.558697 °	10
14	0.62	0.65	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.494468 ° -121.558577 °	38.494037 ° -121.558192 °	16
15	0.65	0.65	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.494097 ° -121.558192 °	38.494097 ° -121.558192 °	19
16	0.66	0.66	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.493917 ° -121.558041 °	38.493917 ° -121.558041 °	18
17	0.69	0.69	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.493596 ° -121.557832 °	38.493596 ° -121.557832 °	35
18	0.71	0.71	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.493392 ° -121.557640 °	38.493392 ° -121.557640 °	15

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
W : Watch/Monitor
N : Not Inspected, see Inspector Comment
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0765 Glide

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Sacramento River						Right	1.74	11/10/2011 11/10/2011	Richard Willoughby	
LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
19	0.78	0.81	Earthen Levee	Trim / Thin Trees	LS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.492392 ° -121.557026 °	38.492034 ° -121.556820 °	36 Y
20	0.87	1.03	Earthen Levee	Trim / Thin Trees	LS	U	Trim trees to at least five feet above ground level.	38.491283 ° -121.556360 °	38.489149 ° -121.555121 °	17 Y
21	0.97	0.97	Earthen Levee	Vegetation	LS	U	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Dense berryvines on landside slope.	38.489962 ° -121.555573 °	38.489962 ° -121.555573 °	81 Y
22	0.99	1.05	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.489705 ° -121.555385 °	38.488990 ° -121.554993 °	8 Y
23	1.08	1.08	Earthen Levee	Trim / Thin Trees	LS	U	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.488503 ° -121.554757 °	38.488503 ° -121.554757 °	37 Y
24	1.10	1.16	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.488279 ° -121.554615 °	38.487465 ° -121.554117 °	38 Y
25	1.15	1.15	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.487653 ° -121.554248 °	38.487653 ° -121.554248 °	39 Y
26	1.16	1.16	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.487473 ° -121.554080 °	38.487473 ° -121.554080 °	9 Y
27	1.19	1.22	Earthen Levee	Encroachments	LS	CO	Buildings	38.487127 ° -121.553910 °	38.486702 ° -121.553652 °	43 Y
28	1.32	1.32	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.485280 ° -121.552860 °	38.485280 ° -121.552860 °	26 Y
29	1.36	1.36	Earthen Levee	Trim / Thin Trees	WS	U	Trim trees to at least five feet above ground level.	38.484877 ° -121.552540 °	38.484877 ° -121.552540 °	7 Y
30	1.41	1.41	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.484316 ° -121.552115 °	38.484316 ° -121.552115 °	4 Y
31	1.44	1.47	Earthen Levee	Trim / Thin Trees	WS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.483925 ° -121.551845 °	38.483530 ° -121.551587 °	5 Y
32	1.50	1.50	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.483170 ° -121.551367 °	38.483170 ° -121.551367 °	42 Y
33	1.54	1.54	Earthen Levee	Vegetation	LS	U	Remove the wild growth other than native grasses from the levee slopes.	38.482590 ° -121.551020 °	38.482590 ° -121.551020 °	29 Y
34	1.60	1.67	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.480913 ° -121.549677 °	38.480993 ° -121.549738 °	2 Y
35	1.60	1.60	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.481841 ° -121.550438 °	38.482028 ° -121.550512 °	31 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
W : Watch/Monitor

N : Not Inspected, see Inspector Comment
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0765 Glide

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River						Right	1.74	11/10/2011 11/10/2011	Richard Willoughby

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
36	1.69	1.69	Earthen Levee	Encroachments	WS	M	Garbage Inspector Comments: Garbage and pruning pile on waterside shoulder.	38.480770 ° -121.549514 °	38.480895 ° -121.549556 °	30 Y
37	1.70	1.70	Earthen Levee	Encroachments	WS	W	Prunings	38.480632 ° -121.549543 °	38.480632 ° -121.549543 °	13 Y
38	1.70	1.73	Earthen Levee	Trim / Thin Trees	WS	M	Trim trees to at least five feet above ground level.	38.480602 ° -121.549523 °	38.480257 ° -121.549458 °	1 Y

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing N : Not Inspected, see Inspector Comment C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	11/10/2011 11/10/2011	Richard Willoughby

Levee Mile Report Line	3
Start Levee Mile	0.12
End Levee Mile	0.19
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking west at trees on landside toe.

richard_f_20111014_893.jpg



Levee Mile Report Line	3
Start Levee Mile	0.12
End Levee Mile	0.19
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking downstream (south) at trees on landside slope & toe.

richard_f_20111014_894.jpg



Levee Mile Report Line	6
Start Levee Mile	0.25
End Levee Mile	0.28
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking northeast at overgrown trees on waterside slope.

richard_f_20111014_887.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
W : Watch/Monitor

N : Not Inspected, see Inspector Comment C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	11/10/2011 11/10/2011	Richard Willoughby

Levee Mile Report Line	6
Start Levee Mile	0.25
End Levee Mile	0.28
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking north at dense trees on waterside slope from fall 2010 inspection.	
richard_f_20111014_888.jpg	



Levee Mile Report Line	6
Start Levee Mile	0.25
End Levee Mile	0.28
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking upstream (north) at dense vegetation and trees from 2011 spring inspection.	
richard_f_20111014_889.jpg	



Levee Mile Report Line	11
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking northwest at trees on landside toe from 2010 fall inspection.	
richard_f_20111014_899.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
W : Watch/Monitor

N : Not Inspected, see Inspector Comment C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	11/10/2011 11/10/2011	Richard Willoughby

Levee Mile Report Line	11
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking downstream (south) at trees on landside slope & toe.

richard_f_20111014_900.jpg



Levee Mile Report Line	11
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking downstream (southwest) at dense vegetation on landside slope.

richard_f_20111014_901.jpg



Levee Mile Report Line	11
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking upstream (northwest) at dense vegetation on landside slope.

richard_f_20111014_902.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
W : Watch/Monitor

N : Not Inspected, see Inspector Comment C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	11/10/2011 11/10/2011	Richard Willoughby

Levee Mile Report Line	20
Start Levee Mile	0.87
End Levee Mile	1.03
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking downstream (south) at dense trees on landside slope and toe.

richard_f_20111014_891.jpg



Levee Mile Report Line	20
Start Levee Mile	0.87
End Levee Mile	1.03
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking upstream (north) at dense trees on landside slope and toe.

richard_f_20111014_892.jpg



Levee Mile Report Line	20
Start Levee Mile	0.87
End Levee Mile	1.03
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking south at dense trees on landside shoulder and slope. (November 2011)

richard_f_20111116_459.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
W : Watch/Monitor

N : Not Inspected, see Inspector Comment C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	11/10/2011 11/10/2011	Richard Willoughby

Levee Mile Report Line	21
Start Levee Mile	0.97
End Levee Mile	0.97
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking west at dense berryvines and wildroses on landside shoulder and slope. (November 2011)

richard_f_20111116_460.jpg



Levee Mile Report Line	22
Start Levee Mile	0.99
End Levee Mile	1.05
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking upstream (northeast) at dense vegetation on waterside slope.

richard_f_20111014_885.jpg



Levee Mile Report Line	22
Start Levee Mile	0.99
End Levee Mile	1.05
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking upstream (north) dense vegetation and trees on waterside shoulder and slope.

richard_f_20111014_886.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
W : Watch/Monitor

N : Not Inspected, see Inspector Comment C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	11/10/2011 11/10/2011	Richard Willoughby

Levee Mile Report Line	23
Start Levee Mile	1.08
End Levee Mile	1.08
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking downstream (south) at trees on landside slope & toe from 2010 fall inspection.

richard_f_20111014_903.jpg



Levee Mile Report Line	23
Start Levee Mile	1.08
End Levee Mile	1.08
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking west at trees on landside slope & toe.

richard_f_20111014_904.jpg



Levee Mile Report Line	23
Start Levee Mile	1.08
End Levee Mile	1.08
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking downstream (southwest) at dense trees on landside slope and toe.

richard_f_20111014_905.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
W : Watch/Monitor

N : Not Inspected, see Inspector Comment C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	11/10/2011 11/10/2011	Richard Willoughby

Levee Mile Report Line	25
Start Levee Mile	1.15
End Levee Mile	1.15
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking downstream (southwest) at wild roses on landside slope & toe.

richard_f_20111014_906.jpg



Levee Mile Report Line	27
Start Levee Mile	1.19
End Levee Mile	1.22
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Looking northwest at buildings along landside toe.

richard_f_20111014_907.jpg



Levee Mile Report Line	29
Start Levee Mile	1.36
End Levee Mile	1.36
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking upstream (north) at dense vegetation on waterside slope.

richard_f_20111014_884.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
W : Watch/Monitor

N : Not Inspected, see Inspector Comment C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	11/10/2011 11/10/2011	Richard Willoughby

Levee Mile Report Line	31
Start Levee Mile	1.44
End Levee Mile	1.47
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking upstream (north) at dense trees on waterside slope.

richard_f_20111014_883.jpg



Levee Mile Report Line	33
Start Levee Mile	1.54
End Levee Mile	1.54
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking downstream (southwest) at trees, vines & wildroses on landside slope & toe from 2010 fall inspection

richard_f_20111014_895.jpg



Levee Mile Report Line	33
Start Levee Mile	1.54
End Levee Mile	1.54
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking downstream (south) at trees, vines & wildroses on landside slope & toe.

richard_f_20111014_896.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
W : Watch/Monitor

N : Not Inspected, see Inspector Comment C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	11/10/2011 11/10/2011	Richard Willoughby

Levee Mile Report Line	33
Start Levee Mile	1.54
End Levee Mile	1.54
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking downstream (south) at dense vegetation on landside slope and toe.

richard_f_20111014_897.jpg



Levee Mile Report Line	33
Start Levee Mile	1.54
End Levee Mile	1.54
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking south at dense vegetation on landside shoulder and slope. (November 2011)

richard_f_20111116_461.jpg



Levee Mile Report Line	34
Start Levee Mile	1.60
End Levee Mile	1.67
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking south at dense trees on waterside slope.

richard_f_20111014_881.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
W : Watch/Monitor

N : Not Inspected, see Inspector Comment C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	11/10/2011 11/10/2011	Richard Willoughby

Levee Mile Report Line	34
Start Levee Mile	1.60
End Levee Mile	1.67
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking east at dense vegetation on waterside slope.

richard_f_20111014_882.jpg



Levee Mile Report Line	36
Start Levee Mile	1.69
End Levee Mile	1.69
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Looking northeast at garbage on waterside slope. (May 2011)

richard_f_20111014_898.jpg



Levee Mile Report Line	36
Start Levee Mile	1.69
End Levee Mile	1.69
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Looking north at garbage and pruning pile on waterside shoulder. (November 2011)

richard_f_20111116_457.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
W : Watch/Monitor

N : Not Inspected, see Inspector Comment C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	11/10/2011 11/10/2011	Richard Willoughby

Levee Mile Report Line	37
Start Levee Mile	1.70
End Levee Mile	1.70
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Looking southeast at pruning piles on waterside shoulder & slope.

richard_f_20111014_890.jpg



Levee Mile Report Line	38
Start Levee Mile	1.70
End Levee Mile	1.73
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking upstream (north) at trees on waterside slope.

richard_f_20111014_879.jpg



Levee Mile Report Line	38
Start Levee Mile	1.70
End Levee Mile	1.73
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking east at trees on waterside slope.

richard_f_20111014_880.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
W : Watch/Monitor

N : Not Inspected, see Inspector Comment C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2011

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	11/10/2011 11/10/2011	Richard Willoughby

Levee Mile Report Line	38
Start Levee Mile	1.70
End Levee Mile	1.73
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking south at dense trees and vegetation on waterside slope. (November 2011)

richard_f_20111116_458.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing N : Not Inspected, see Inspector Comment C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable W : Watch/Monitor